





F16.3

DETECT CLOSED-LOOP POWER CONTROL MEASURE INDICATIONS -96 OF THE DETECTED POWER CONTROL COMMANDS COMPARE MEASURED INDICATION VALUES WITH A THRESHOLD VALUE SELECTABLY GENERATE
A DATA COMMUNICATION
PERMISSION COMMAND

F16. 4